Qty:

Um:

Each

: BEARING ASSEMBLY

: D3183045

: 26/09/2006

: N/A

: C1

- D3183 REV C1

Date

Tuesday, 26/09/2006 10:32:38 AM

User:

Linda Lacelle

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Customer **Job Number** : CU-DAR001 Dart Helicopters Services

: 28721 : 11136

Estimate Number

P.O. Number This Issue

: 26/09/2006

S.O. No. :

: NC

Prsht Rev. First Issue **Previous Run**

: //

: 28653

: MACHINED PARTS Type

Written By **Checked & Approved By**

Comment

: Est A04.02.18 New issue KJ/DS

Additional Product

Job Number:



Seq. #:

Description: Delrin Round Bar 1"

MDELRINR1000 1.0

Comment: Qtv

0.0350 f(s)/Unit Total:

0.1399 f(s)

Delrin Round Bar 1" Material: \$\times 1.00 Delrin Rod (M-DELRINAR1.000) Identify as D3183-9

Batch:

2.0

HARDINGE

HARDINGE CNC LATHE SMALL

Comment: HARDINGE CNC LATHE SMALL

Turn D3183-9 Cap as per Folio FA388

Deburr

3.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

SECOND CHECK

Comment: SECOND CHECK

5.0

D31835

Bearing

Comment: Qty.:

D3183-5

1.0000 Each(s)/Unit

Total:

4.0000 Each(s)

Pick:

Qty Part Number

Description

Bearing



Date: Tuesday, 26/09/2006 10:32:38 AM Linda Lacelle User: **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: BEARING ASSEMBLY Job Number: 28721 Part Number: D3183045 Job Number: Description: Seq. #: **Machine Or Operation:** SMALL & MEDIUM FAB RESOURCE 1 6.0 SMALL FAB 1 865-26 Comment: SMALL & MEDIUM FAB RESOURCE 1 Press D3183-5 Bearing into D3183-9 Cap as per Dwg D3183. INSPECT WORK TO CURRENT STEP 7.0 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 PACKAGING 1 8.0

Comment: PACKAGING RESOURCE #1
Identify and Stock

Location:____

9.0 QC21

FINAL INSPECTION/W/O RELEASE

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



1, 76.09/26